Bruhath Bangalore Mahanagara Palike

Inspection Report

1	Name of work	Providing RCC drain, balance portion of 9th cross, Brindavana nagara in Ward No.17
2	Administration Approval and Date	JC/RRNZ/AS/651/2012-13, Date:21.12.2012
3	Technical Sanction Estimate No. & Date	EE/RRND/TS/577/2012-13, Date:09.01.2013
4	Estimate Amount	Rs.10.00 Lakhs
5	Job Code No	017-13-000014
6	P-Code	P-1771
7	Agreement No and Date	EE/RRND/AG No./693/2012-13, Date:19.03.2013
8	Work order Number and Date	EE/RRND/WO/693/2012-13, Date:19.03.2013
9	Contract Amount as per Agreement	Rs.9,08,235=00
10	Bill Amount	Rs.9,08,235=00
11	B.R No and Date	74/2015-16, Date:31.07.2015
12	Agency	M/s Chowdewshwari Constructions
13	M.B Number and Page No of Measurement records	1763, Page No.176259 to 176264
14	Date of Inspection	26.08.2015
15	Enclosures	(1) Exract of MB 1763, Page No.176265 (2) 04 No. of photos taken during Inspections
16	Inspection Report	The above site has been Inspected by me along with the Concerned Engineer. The measurements have been checked by me, which are susceptible for measurements & found to be Satisfactory

EE (P) RR Nagara

26/8/2015

(R.Sathyanarayana)
Inspection Report officer

Inspection Report officer

Scanned by CamScanner

M.A.I e 116)

Measurement Book No. A/10 176265

Serial No.....

Name of work..... Sketch showing providing R.C.C. drain Balance Portion From..... To.....

Name of Contractor of nature of Agency..... & 9th cross Brindavan nagar

Date of commencement of work..... in Ward No 17

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8



Received

26/8/2015

R. SATHYANARAYANA
INSPECTION OFFICER

Scanned by CamScanner

Providing RCC drain balance portion of 9th cross, Brindavan nagara in Ward No.17

26/8/2015

R. SATHYANARAYANA
INSPECTION OFFICER

Scanned by CamScanner

Providing RCC drain balance portion of 9th cross, Brindavan nagara in Ward No.17

26/8/2015

R. SATHYANARAYANA
INSPECTION OFFICER

Scanned by CamScanner